

SERVICE BULLETIN



THE
Indian
MOTORCYCLE COMPANY

Bulletin No. SVB-122

Model SE-74

Subject High-Low Beam
Switch Modification

Date 11-6-72

SE-74 HIGH-LOW BEAM SWITCH MODIFICATION

To eliminate the headlight and taillight blowing at high engine speed the previous Service Bulletin #119 must be performed. This eliminates the reactor from the electrical system.

The high-low beam switch assembly must be disassembled and the inside contactors of the high-low beam switch must be soldered together as the drawing below.



