

# SERVICE BULLETIN



THE  
*Indian*  
MOTORCYCLE COMPANY

**Bulletin No.** SVB-141;

**Model** ME-100

**Subject** Ignition Timing

**Date** July 5, 1973

## ME-100 IGNITION TIMING

In the F500K engine Owner's Handbook that is supplied with each 100cc motorcycles on Page 4, Item 7, the measurement for the ignition timing is wrong.

The book now reads "The standard ignition timing is  $25^{\circ}$  B.T.D.C., 0.162"

(2.6mm) measured at the piston." The correct ignition timing should be

$25^{\circ}$  B.T.D.C, 0.102 (2.6mm) measured at the piston.

