SERVICE BULLETIN



FORM: 4500

Bulletin No. SVB-126

Model ALL

Subject Shipping Oil Plug

Date 1-10-73

REMOVING BROWN SHIPPING OIL PLUG

On all model engines in the Indian line (P450, P470 and 125) the motorcycles are shipped with a brown shipping oil plug in the transmission. This plug is for shipping purposes only. It is not vented. This plug <u>must</u> be removed from the engine prior to delivery to your customers. This plug should be replaced with the black vented plug provided with each motorcycle. The part number of the black oil plug is M5-25. The gasket for this plug is M5-26.

