

# SERVICE BULLETIN



THE  
*Indian*  
MOTORCYCLE COMPANY

**Bulletin No.** SVB-140

**Model** All

**Subject** Spark Arrester

**Date** 6/6/73

## ALL MOTORCYCLES EQUIPPED WITH SCREEN TYPE SPARK ARRESTER

On all new bikes equipped with the screen type spark arrester, the screen will be plugged up with fiberglass after approximately one hour of use because of the loose fiberglass particles blowing against the screen. The screen (part number 11104118) MUST be cleaned out or replaced. The problem will not reoccur after one hour's use because all the loose particles will have come out of the muffler by then.

