

SERVICE BULLETIN



THE

Indian

MOTORCYCLE COMPANY

Bulletin No. SVB-154

Model 125/5 ENGINE

Subject CRANKSHAFT
SEAL CHANGE

Date MARCH 21, 1974

125/5 ENGINE CRANKSHAFT SEAL CHANGE

When installing new crankshaft seals in the 125/5 engine, be certain to use the new black rubber seal, Part No. 23001188 in the magneto side of the engine, and the blue rubber seal, Part No. 23001022, in the transmission side of the engine only.

Pre-lubricate the seals, crankshaft, and engine cases with grease before installing the new seals.

