SERVICE BULLETIN



Bulletin No. SVB-169

Model ML-100

Subject PARTS CHANGES

Date AUGUST 23, 1974

PARTS CHANGES

This is to inform you of a phase change on the ML-100. Motorcycles with serial numbers 2314G00001 and up will have the following part changes:

1.	Engine with more H.P. refer to SVB-157/B	P/N	#92001500
2.	Nylon throttle assembly	P/N	#13004120
3.	Throttle Cable	P/N	#12004022
4.	Soft rubber hand grips, R/H	P/N	#13004170
5.	Soft rubber hand grips, L/H	P/N	#13004169

Refer to SVB-163 for an explanation of serial number phase changes.

