

MOTORCYCLE COMPANY • 1535 West Rosecrans Avenue, Gardena, Calif. 90249

SVB-115 6/20/72 Page 1 of 3

> Carburetor problems with the UB20S on the SE-54.

This is general information which would pertain to any carburetor and model Motorcycle.

GAS TANK

Before setting up the Motorcycle to run, the gas tank should be inspected for any foreign dirt or rust. If finding any dirt or rust the gas tank should be completely flushed clean. be done by several methods. It is recommended that the gas tank be removed and navel jelly or any other rust preventive be poured into the tank, then place a cup full of small clean stones (gravel) and shake vigorously for approximately 10 minutes. Remove the navel jelly and stones and flush clean with gas. Then reinstall the gas tank and immediately fill with a gas- oil mixture to prevent recontamination. The fuel lines and pet cocks sediment bowl should be cleaned out and at this time we recommend that you install an inline Carter filter, these are available from Webco, Inc.

CARBURETOR

If the Motorcycle has been run prior to flushing out the gas tank and there is a possibility that the carburetor has dirt or rust in it, the carburetor should be removed from the engine and then completely torn apart and all of the metal parts of the carburetor placed in carburetor cleaner. Leave all of the parts in the cleaner for at least 4 hours. Remove the parts from the cleaner and completely flush clean with gas. With high pressure air blow out all of the passages. In regards to the pilot circuit of the carburetor physically clean them out with a fine wire and then blow the passages out with air again. Physically clean out all the orifice holes in the jets particularly the pilot jet. Completely reassemble the carburetor and place back on the inlet manifold.

