



FACTORY SERVICE BULLETIN

Number	SVB-169A
Model	ALL "M" SERIES
Subject	PARTS CHANGES

This bulletin supplements SVB-169, August 23, 1974. Please make the following additions to PB-113, ME FRAME ASSEMBLY PARTS LIST, as follows:

ITEM	PAGE/REF #	PART NBR.	DESCRIPTION	QTY.	REMARKS
1.	3. 1-1-1	1111 4001	HANDLEBAR ASSY	1	For nylon throttle assembly (knurled)
2.	3. 1-9-1	1300 4139	THROTTLE CABLE ASSY	1	For nylon throttle (ME125B)
3.	3. 1-20-1	1300 4171	BOOT, Throttle Cable	1	For nylon throttle
4.	3. 1-22-1	1300 4127	SCREW, Phillips 6 x 20	2	
5.	3. 1-24-1	1300 4170	GRIP, Handlebar, right	1	"smooth" grip
6.	3. 1-24-2	1300 4169	GRIP, Handlebar, left	1	"smooth" grip
7.	3. 1-23-1	1300 4120	THROTTLE ASSY, Nylon	1	Includes items 8-13
8.	3. 1-25	1300 4123	. ADJUSTER, Cable, 10 x 1.0 x 20	1	For nylon-type throttle cable
9.	3. 1-26	1300 4124	. NUT, Adjuster Lock, 10 x 1.0 x 12	1	For nylon-type throttle cable
10.	3. 1-27	1300 4126	. NUT, Acorn, 6mm	2	For nylon throttle
11.	3. 1-28	1300 4121	. THROTTLE BODY, Upper, nylon	1	
12.	3. 1-29	1300 4125	. CAM, Throttle	1	For nylon throttle
13.	3. 1-30	1300 4122	. THROTTLE BODY, Lower, nylon	1	
14.	3. 1-31	1300 4128	BOOT, Cable, accordian-type	2	
15.	3. 1-32	1300 4129	BOOT, Lever, accordian-type	2	

NOTE: Items #1 through #7 do not supersede existing pieces.
Items #8 through #15 are new additions supplementing nylon throttle addition.

An illustration of the added/changed parts is shown on the reverse side of this bulletin. In order to aid you in identification to correct your parts list, the page/reference number code is as follows:

Reference 3. 1-1-1 indicates there is no additional drawing, it is an added part that looks much like the original which can be found by referring to page 3, Fig. 1, Index number 1.

